

This Information Is Provided By
CBTricks.com

Cobra 138XLR / 139XLR Technical Bulletin 1211A

Liability of damages to any equipment is the sole responsibility of the user! Downloading, viewing, or using any information provided on these pages automatically accepts the user to the terms of this agreement!

Modifications are provided for information purposes only!

Supporters of CBTricks.com paid for the hosting so you would have this file.

CBTricks.com is a non-commercial personal website was created to help promote the exchange of service, modification, technically oriented information, and historical information aimed at the Citizens Band, GMRS (CB "A" Band), MURS, Amateur Radios and RF Amps.

CBTricks.com is not sponsored by or connected to any Retailer, Radio, Antenna Manufacturer or Amp Manufacturer, or affiliated with any site links shown in the links database. The use of product or company names on my web site is not endorsement of that product or company.

The site is supported with donations from users, friends and selling of the Site Supporters DVD's to cover some of the costs of having this website on the Internet instead of relying on banner ads, pop-up ads, commercial links, etc. Thus I do not accept advertising banners or pop-up/pop-under advertising or other marketing/sales links or gimmicks on my website.

ALL the money from donations is used for CBTricks.com I didn't do all the work to make money (I have a day job). This work was not done for someone else to make money also, for example the ebay CD sellers.

All Trademarks, Logos, and Brand Names are the property of their respective owners.

This information is not provided by, or affiliated in any way with any radio or antenna Manufacturers.

Thank you for any support you can give.

For information on how to Support CBTricks.com

<http://www.cbtricks.com/support/>

DYNASCAN SERVICE OPERATION

Cobra Communications

COBRA FIELD BULLETIN

THIS BULLETIN REPLACES #1211

SUBJECT: RELAYS ON THE COBRA 138XLR AND THE COBRA 139XLR

SYMPTOM: AFTER THE SET HAS BEEN ON FOR A PERIOD OF TIME THE RELAY DOES NOT KEY INTO THE TRANSMIT MODE.

SOLUTION: CHECK TO SEE IF RELAY CLOSES AT $10.5 \pm .1$ VDC AT ROOM TEMPERATURE. IF THE RELAY DOES NOT MEET THIS REQUIREMENT, REPLACE RELAY WITH ZRLY 027001 DYNASCAN PART No. 441-019-9-001.

REASON FOR RE-ISSUE: 12-15 minute test at 11.7VDC no longer required.

NOTE:

1. THE ONLY RELAY IN DYNASCANS STOCK FOR THE COBRA 138XLR/139XLR IS THE ZRLY 027001, DYNASCAN PART No. 441-019-9-001.
2. THIS MODIFICATION IS DONE IN WARRANTY DURING THE WARRANTY PERIOD WHEN THE CUSTOMER COMPLAINS.

CJH/IN
#1211-A
7/29/77