

SPECIFIC TUNE-UPS

Hygain IV Mdl. 673, Base: RV103-AMC, RV101-Sq Rng, RV104-Tx Mtr, RV102-Rx Mtr.
Tune L-111, L-109, L-108 for max RF forward output. (*)

Kraco KB2345, Base: RV2-AMC, RV1-Sq Rng, RV3-Rx Mtr, RV4-Tx Mtr.
Tune L-7, L-8, L-9 for max RF forward output: 12W final push it! (*)

(*) Xtals for extra Fo's - Vol. 1; Low Fo conversion Vol. 11, pg. 36;
Xtal switching Vol. 15, pg. 64. --both units...

G.E. 3-5813B PLL02A: RV1-Sq Rng; RV2-AMC (Don't defeat); RV3-Rx Mtr; RV4-Tx Mtr;
RV501-AWI adjust. Tune L12, L11, and L7 for max forward.
12W Final, change insulator to mica type.

LAFAYETTE OWNERS

As most of you know by now Lafayette is no longer in the C.B. business.
But....have found the source for parts, manuals, service...(U.S. MODELS ONLY)

Terryville Electronics, Inc.; 693 Old Town Road; Terryville, New York 11776
Ph. No. 516-473-0192 Re: Ellen at TEI.

COLT OWNERS

People have been writing to find the source of parts for Colts:
Had a time finding it, but was pleasantly surprised! CO-OPERATION in
capitol letters! (U.S. MODELS ONLY)

Cibcoa; 625 Academy Drive; Northbrook, Illinois 60062-2472
.... Re: John Malloy...(Suggest you write as are also a LARGE electronics
wholesale ONLY distributor) Mark letter ATTN: John Malloy...

SBE OWNERS

All I received was a change of address, no particulars!

SBE, Inc.; 4700 San Pablo Ave.; Emeryville, Calif. 94608 Ph. No. 415-652-1805

PALOMAR OWNERS

All I received was address, no particulars!

Palomar Electronics Repair Service; 1320 Grand Ave.; San Marcos, Calif. 92069
Ph. No. 619-744-0720

TROUBLE-SHOOTING TABLES

The following 5 pages are re-written/modified trouble-shooting charts
for use by the technician; use in correlation with original schematic if
needed. In most cases the chassis are identical.