



EQUIPMENT AFFECTED

Messenger 323, Part No. 242-0153-002

REASON FOR REVISION

Improve tight squelch operation.

REVISION

Replace R18 with a 39K ohm resistor.

PARTS REQUIRED

<u>QTY</u>	<u>PART NUMBER</u>	<u>DESCRIPTION</u>
1	569-1004-393	Resistor, 39K Ω , 1/2 W, 10%

CHANGE ACTION

Change as necessary. This change is included in the E model.