



EQUIPMENT AFFECTED

Johnson Transceiver Tester
Part No. 250-0718-001

REASON FOR REVISION

Unable to measure percent of modulation in a mobile installation.

REVISION

Connect a 1K ohm resistor across the ANTENNA connector by soldering one end of the resistor to the center conductor and the other end of the resistor to the antenna connector ground lug.

PARTS REQUIRED

<u>QTY</u>	<u>PART NUMBER</u>	<u>PART DESCRIPTION</u>
1	569-1004-102	1.0K Ω \pm 10% 1/2 W

CHANGE ACTION

Make this change as required. This change has been incorporated in "D" models.