CIRCUIT DIAGRAM FOR COBRA 29