



**Consumer Response Group**

6500 W. Cortland Street \* Chicago, IL 60707 \* Phone: 773-889-8870 \* FAX: 773-622-2269  
-----

October 3, 2000

Page 1 of 1

## **TECHNICAL SERVICE BULLETIN 10002**

**MODEL(S):** 148GTLST, 148NWST

**DESCRIPTION:** All channels are locked on the same transmit frequency.

**ACTION:** Replace R130, which is located at the left edge of the PCB, near the PLL chip (IC1, MB8719). Use a 10 ohm 1/2W resistor.

**ADJUSTMENTS:** None.

**NOTES:** None.